

Local Notice to Mariners

Unlit Mooring Buoy-Middle Arm Darwin Harbour

To	Port Users	Location	Darwin Harbour
Date of issue	22 September 2026	Ref number	Local NtM 2026-088 (T)

Notification

Port users are informed to exercise caution in the vicinity of Middle Arm.	
Mooring buoy is reported unlit [missing light]	
Date of activity:	22 September 2026
Location of activity:	Middle Arm, Darwin Harbour
Description of Activity:	Mooring Buoy in Middle Arm reported unlit. Location 12°34.349'S * 130°52.427'E
Conducted by:	SERCO
Phone	Sean Barker 0461 499 558
Additional information	
Cancel this notice on:	TBA

Sri Srinivas
A/ Regional Harbour Master