

NORTHERN TERRITORY COASTAL NOTICE TO MARINERS

BEACONS BUFFALO CREEK

TO: USERS NT COASTAL WATERS

FROM: DMS

REF: NtM 2019/006

DATE: 20 June 2019

Mariners are advised of the following changes to navigation beacons in Buffalo Creek:

Remove	Beacon (without top mark) with light	<i>Fl.5s</i>	12° 20.530'S 130° 55.650'E
	Beacon (without top mark) with light	<i>Fl.5s</i>	12° 20.360'S 130° 55.705'E
Insert	Starboard beacon (without top mark) with light	<i>Fl.G.5s</i>	12° 20.570'S 130° 55.588'E
	Port beacon (without top mark) with light	<i>Fl.R.5s</i>	12° 20.613'S 130° 55.583'E
	Starboard beacon (without top mark) with light	<i>Fl.G.5s</i>	12° 20.569'S 130° 55.760'E
	Port beacon (without top mark) with light	<i>Fl.R.5s</i>	12° 20.582'S 130° 55.795'E
	Starboard beacon (without top mark) with light	<i>Fl.G.5s</i>	12° 20.416'S 130° 55.798'E
	Port beacon (without top mark) with light	<i>Fl.R.5s</i>	12° 20.423'S 130° 55.850'E
	Starboard beacon (without top mark) with light	<i>Fl.G.5s</i>	12° 20.198'S 130° 55.830'E
	Port beacon (without top mark) with light	<i>Fl.R.5s</i>	12° 20.202'S 130° 55.899'E

Captain Tony O'Malley
Director Marine Safety