

NOTICE TO MARINERS

DECLARED PORT DEPTHS

TO: PORT USERS

FROM: RHM

REF: NtM 2021/002(T)

DATE: 18 January 2021

Local Notice 002(T) / 2020 is hereby cancelled.

Mariners are advised that the depths below Lowest Astronomical Tide (LAT) are amended as follows:

Wharf	Metre Mark		Depth (m)	Comment
	From	To		
Middle Passage Deep Water Route			13.3	Minimum depth in the area defined by buoys 1, 2, 3 and 4
EAW	0	50	12.1	Zero metre mark at the eastern end
	50	100	12.1	
	100	150	12.0	
	150	200	12.8	
	200	250	12.8	
	250	300	12.8	
	300	350	13.4	
	350	400	13.4	
	400	450	13.5	
	450	500	13.6	
	500	550	13.6	
	550	600	13.6	
	600	650	12.1	
	650	700	12.1	
	700	750	12.0	
	750	800	12.0	
	800	850	12.0	
850	865	11.7		
			11.7	Controlling depth adjacent to # 12 buoy for EAW approach
ABF	Berth 1		10.0	
	Berth 2		10.0	
Bladin Point	Channel		13.5	
	Swing Basin		12.5	
	Alongside ILNG		12.3	
	Alongside ILPG		12.7	
DMSB	Channel		7.4	Zero metre mark at the southern end
	Swing Basin		7.5	
	0	50	8.5	
	50	100	8.5	
	100	150	7.5	
	150	200	7.4	

	200	260	7.5	
	260	265	7.5	
MUBR	Channel		1.1	
	Berth		1.1	
Hudson Creek	Seaswift Main		-3.4	
	The Pocket		-4.7	
	Sitebark Wharf		-4.6	
	River Wharf		-2.0	
	The Slot		-2.6	
	RUB Contracting		-4.5	
	Top End Marine Supply Base		-3.1	
FHW	0	50	9.7	Zero metre mark at the eastern end
	50	100	9.8	
	100	150	10.4	
	150	200	11.2	
	200	250	10.9	
	250	300	10.7	
	300	Dolphin	11.8	
SHW	0	50	11.4	Zero metre mark at the eastern end
	50	100	6.6	
	100	150	4.3	
	150	200	4.3	
	200	250	4.5	
	250	300	5.0	
Seaswift City	Seaswift Berth 4		-2.0	
	Seaswift Berth 3		-1.4	
	Seaswift Berth 2		-1.1	
	Seaswift Berth 1		-1.6	
FBMB approach channel			-1.6	
Fisherman's Wharf	0	100	1.7	Zero metre mark at the seaward end
	100	150	1.4	
	150	185	1.6	
	185	199	0.0	
Raptis Wharf			0.0	
Tasmanian Seafoods	North		-2.6	
	Centre		-1.6	
	South		-0.2	
DLNG	Alongside		14.4	
	Swing Area		11.9	

Captain Anil Chadha
Regional Harbourmaster