

Local Notice to mariners

Update: Wickham Shoal Nth Cardinal Buoy

To	Port Users	Location	Darwin Harbour
Date	15 February 2024	Ref number	2024 – 004 T

Notification

Port users are advised that the Wickham Shoal Nth Cardinal Buoy has been repaired although with a slightly different display to what was previously there.

Capt. Anil Chadha
Regional Harbourmaster

