

NORTHERN TERRITORY COASTAL NOTICE TO MARINERS

LATERAL BUOYS MEDINA INLET & APSLEY ST

TO: USERS NT COASTAL WATERS

FROM: DMS

REF: NtM 2019/002

DATE: 27 MARCH 2019

Mariners are advised of the following changes to navigation buoys in Medina Inlet and Apsley Strait:

Insert	Port lateral light buoy with topmark	<i>Fl.R.4s</i>	11° 44.218'S 130° 37.688'E
Move	Starboard lateral light buoy with topmark	From	11° 46.013'S 130° 40.186'E
		To	11° 46.242'S 130° 40.137'E
	Port lateral light buoy with topmark	From	11° 43.575'S 130° 36.799'E
		To	11° 43.779'S 130° 37.127'E
	Starboard lateral light buoy with topmark	From	11° 43.412'S 130° 35.658'E
		To	11° 43.550'S 130° 35.880'E
	Port lateral light buoy with topmark	From	11° 43.416'S 130° 35.452'E
		To	11° 43.650'S 130° 35.650'E

Captain Tony O'Malley
Director Marine Safety