

Local Notice to mariners

Special Purpose General Beacon LOA2A not working

To Port Users	Location Darwin Harbour
Date 9 December 2022	Ref number 2022 – 058 T

Notification

Port users are advised that special purpose general beacon LO2A close to INPEX swing basin is temporarily not working

Position of Light

Latitude: 12 0 30.46S

Longitude: 130 55.26E

Characteristics: F Y

Mariners are advised to exercise caution

Capt. Anil Chadha

Regional Harbourmaster