

## NOTICE TO MARINERS

### SPECIAL MARKER REPORTED UNLIT

---

**TO: PORT USERS**

**FROM: RHM**

**REF: NtM 2017/012(T)**

**DATE: 08 February 2017**

---

Mariners are advised that a special marker buoy at East Point to mark Power & Water outfalls has been reported unlit

Type	Position	Light
Yellow Special Mark 1300mm Buoy	12° 24.067'S 130°49.325'E	Fl. Y. 4s

Mariners are advised to navigate with additional caution in the vicinity and are requested to report the status of the light to [NtM@nt.gov.au](mailto:NtM@nt.gov.au).



*East Point Buoy*

**Captain Tony O'Malley**  
Regional Harbourmaster