

# Coastal Notice to mariners

## Medina Inlet Light Extinguished

<b>To</b>	Coastal Mariners	<b>Location</b>	Medina Inlet Entrance
<b>Date</b>	22 August 2022	<b>Ref number</b>	NtM 2022/ 024 (T)

### Notification

Coastal Mariners are advised a report has been received informing Coastal Mariners that the Starboard Lateral Mark on entering the Medina Inlet is extinguished, Mariners are advised to proceed with addition caution when entering the Inlet during the hours of darkness.

Please forward additional reports to [marinesafety@nt.gov.au](mailto:marinesafety@nt.gov.au) and [NtM@nt.gov.au](mailto:NtM@nt.gov.au)

Regards

Capt. Anil Chadha

Director of Marine Safety NT

SMALL WAVE BUOY  
SOFAR SPOTTER. ~420mm  
diameter. FI 2.5s Y.

Surface Float, orange or yellow. 300mm diameter

Ocean Surface: ~ 93 m

SS Swivel

SS Swivel

20m: 6mm Lead Core Rope

115 m: 8mm  
Aquatec  
3 Strand Rope

Subsurface float  
~ 3.7 kg buoyancy

5 m

Galv Swivel 13 mm

Galv Chain to anchor weight

~ 70-80 kg Steel

Mooring: Small Wave Buoy: SOFAR SPOTTER  
Location: Goodrich Bank 3  
deployed 02/05/2022  
recovered ~

**Deployment Information:**

Deployed Lat: 10° 19.043' S  
Deployed Lon: 129° 57.169' E  
Serial# SPOT-1294

Scale: Not To Scale  
Drawn: 05/05/2022  
M. Hatcher  
Revision: 01



NOT TO SCALE