

# Local Notice to Mariners

## DECLARED DARWIN PORT DEPTHS 2024

**To:** Port Users                      **Issued By:** Regional Harbour Master  
**Date:** 16 January 2024           **Ref number:** 2024 / 003 (T)

### Notification

Local Notice 2023/004 (T) is hereby cancelled.  
Mariners are advised that the depths below Lowest Astronomical Tide (LAT) are amended as follows:

Wharf	Metre Mark		Depth (m)	Comment
	From	To		
Middle Passage Deep Water Route	Minimum depth in the area defined by buoys 1, 2, 3 and 4		12.5	Patch at the edge of channel
EAW	0	50	12.3	Zero metre mark is at the eastern end
	50	100	12.1	
	100	150	11.8	
	150	200	12.5	
	200	250	12.6	
	250	300	12.6	
	300	350	13.0	
	350	400	13.3	
	400	450	13.4	
	450	500	13.4	
	500	550	13.3	
	550	600	13.5	
	600	650	12.0	
	650	700	11.8	
	700	750	11.8	
	750	800	11.9	
	800	850	12.0	
	850	865	11.0	
	Controlling depth adjacent to dry bulks berth		11.4	
	Controlling depth adjacent to # 12 buoy for EAW approach		11.7	
ABF	Berth 1		10.0	
	Berth 2		10.0	
Bladin Point	Channel		13.5	
	Swing Basin		12.0	
	Alongside ILNG		12.1	
	Alongside ILPG		12.1	
DMSB	Channel		7.2	
	Swing Basin		7.2	

DMSB (cont'd)	0	50	8.3	Zero metre mark is at the southern end
	50	100	8.2	
	100	150	7.2	
	150	200	7.2	
	200	260	7.1	
	260	265	6.8	
MUBR	Channel		1.1	
	Berth		1.1	
Hudson Creek	Top End Marine Supply Base		-3.3	
	RUB Contracting		-4.0	
	The Slot		-2.0	
	River Wharf		-3.9	
	Sitebark Wharf		-4.7	
	The Pocket		-4.6	
	Seaswift Main South side of the pocket		-5.0	
	Seaswift Main North side of the pocket		-4.6	
FHW	0	50	9.1	Zero metre mark is at the eastern end
	50	100	9.4	
	100	150	10.4	
	150	200	11.4	
	200	250	10.3	
	250	300	10.8	
	300	Dolphin	12.5	
SHW	0	50	11.3	Zero metre mark is at the eastern end
	50	100	7.1	
	100	150	4.5	
	150	200	3.5	
	200	250	4.0	
	250	300	4.7	
Seaswift City	Seaswift Berth 4		-2.0	Southern end berth
	Seaswift Berth 3		-1.3	
	Seaswift Berth 2		-1.1	
	Seaswift Berth 1		-1.1	
Francis Bay Mooring Basin	FBMB Approach channel		-1.6	
Fisherman's Wharf	0	100	1.4	Zero metre mark is at the seaward end
	100	150	1.6	
	150	185	1.5	
	185	199	1.2	
Raptis Wharf			0.0	
Tasmanian Seafoods	North		-2.6	
	Centre		1.1	
	South		0.8	
NT Marine Facility	Travel Lift Pocket		-3.4	
DLNG	Alongside		14.0	
	Swing Area		11.9	

**Captain Anil Chadha**  
Regional Harbour Master