

Local Notice to Mariners

Bayu Undan Pipeline – Update on Marker Buoys

To	Port Users	Location	Vicinity of Darwin LNG Facility
Date of issue	15 October 2024	Ref number	Local NtM 2024 - 096

Notification

Port Users are advised that DVO JV have removed one marker buoy from near the Bayu Undan pipeline in the vicinity of the DLNG facility.

Date of activity:	15 October 2024									
Time of activity:										
Location of activity:	2 marker buoys remain in the vicinity of the DLNG facility adjacent to the Bayu Undan pipeline, in the below locations. <table border="1"><thead><tr><th></th><th>Latitude</th><th>Longitude</th></tr></thead><tbody><tr><td>Buoy 1</td><td>12° 31.5967 S</td><td>130° 51.5936 E</td></tr><tr><td>Buoy 2</td><td>12° 31.6007 S</td><td>130° 51.5806 E</td></tr></tbody></table>		Latitude	Longitude	Buoy 1	12° 31.5967 S	130° 51.5936 E	Buoy 2	12° 31.6007 S	130° 51.5806 E
	Latitude	Longitude								
Buoy 1	12° 31.5967 S	130° 51.5936 E								
Buoy 2	12° 31.6007 S	130° 51.5806 E								
Assets/ Vessels involved										
Description of Activity:	Two marker buoys, yellow in colour, fitted with yellow FI lights are in position near the Bayu Undan pipeline in the vicinity of the DNLG facility.									
Conducted by:	DVO JV									
Communication : Radio										
Mobile										
Additional information	DVO JV – Operational department contact details: Works Manager : +61 400 449 696 / +61 447 595 687									
Cancel this notice on:	1 st week of December 2024 (tentative end of operations)									

Capt. Anil Chadha

Regional Harbourmaster – Darwin
