

- Construction Notes**
- Permitted clearing area digital linework to be obtained from DLRM
 - Contractor to inspect & flag clearing area prior to commencement of works
 - 100m buffer along creek on western boundary to be confirmed prior to commencement of works
 - 100m buffer from edge of sinkhole on northern property boundary to be confirmed prior to commencement of works
 - Early Nov 2014 – clear paddock & leave felled veg in situ until Sep 2015
 - Clearing method – chain using two bulldozers equipped with GPS
 - Early Sep 2015 – windrow felled veg at right angles to contour & burn (Permit to Burn to be obtained from Bushfires NT)
 - Early Sep 2015 – construct diversion banks on boundaries
 - Early Nov 2015– prepare soil using offset disc plough to rip & mound across slope at 4.5m spacing
 - Early Nov 2015 – lay irrigation, plant mango trees & seed inter-row spacings with Jarra grass
 - 100m wide wildlife corridor to be permanently retained & regularly maintained
 - Firebreaks 10m wide, maintained using slasher.

Contacts

Site Manager:	John Smith	ph: 0400 000 000
Contractor:	Smith Dozers	ph: 0411 111 111
Property Owners:	Gillard & Co	ph: 0422 222 222
DLRM:		ph: (08) 8999 4454

Legend

- Sinkhole
- Diversion Banks
- ➔ Direction of Slope
- Contours (2m interval)
- Deep Red Kandasol soils
- Sandy Brown Kandasol soils
- Buffer 100m
- ▭ Property Boundary
- ▭ Cleared area, 10m firebreak


Data Source

Boundary/Contours:
Dept Lands Planning Environment
© Northern Territory of Australia
Background Image: Google Earth - date

Erosion and Sediment Control Plan
Date: 26/06/2014
Drawing No: ESCP-003

NT Portion 1234
101 Territory Rd, Katherine
Clearing Area 2
Mango Orchard
Map 3 of 3

EXAMPLE ONLY
NOT FOR USE



Sample map A3 size. Produced by:
Department of Land Resource Management (DLRM)
For more information about native vegetation
www.lrm.nt.gov.au/natveg